

Ultra Cut® XP3013 - 50cm wide

STEP BY STEP

Step 1

Cut your design in mirror image Film blade required (90 - 100gf)

Step 2

Weed away any excess material

Step 3

Place transfer face down onto the garment with the transparent backing on top and press for 15 seconds at 165°C.

Step 4

Remove the transparent backing hot (Sky Blue and Opaque Sky Blue - Remove the transparent backing cold)

DURABILITY	MICRONS	FINISH	TACK	PEEL	PU or PVC
80°C	100μ	Matt	Very High	Hot Sky & Opaque Sky - Cold	PU

PRODUCT INFORMATION

SIZE: 50cm wide x 5 & 25m rolls

CUTTING FORCE: 90 - 100gf (Film Blade)

TRANSFER LAYERING: Yes (excluding metallics, fluorescents and sky)

PLEASE NOTE: Re-press for 5 seconds after the removal of the backing when multi transfer layering.

SUITABLE FOR

- ▶ Cotton
- ▶ Polyester
- ▶ Polyester/Cotton

Uncoated garments only

01332 855 085

www.xpres.co.uk

sales@xpres.co.uk

www.xprestechnical.co.uk

Phone:

TRANSFER SETTINGS

TIME	15 seconds	
TEMPERATURE	165°C	
PRESSURE	Medium	
PEEL	Hot (Sky & Opaque Sky - Cold)	

CARE INFORMATION

- ▶ Up to 80°C (Up to 60°C inside out for opaques and multi transfer layering)
- ▶ Can be dry cleaned
- ▶ Can be tumble dried
- **▶ Do not** iron

PLEASE NOTE: A4 samples are available free of charge upon request, for larger samples 1m rolls are available for purchase.

PLEASE NOTE: The sellers and manufacturers maximum obligation shall be to replace any product that has been proven to be defective. Neither the seller nor the manufacturer of Ultra Cut shall be liable for any injury direct or consequential, arising out of the use of, or inability to use this range. Ultra Cut has been tested using Kustom Kit garments, when applying to other garment brands results may vary, testing prior to purchase is recommended.