

JOBMAN

Size chart in cm



Brand; Jobman workwear
Style; 1201 Softshell jacket

Position	XS	S	M	L	XL	2XL	3XL	4XL
1/2 CHEST	50	54	58	62	66	70	74	78
1/2 BOTTOM	48	52	56	60	64	68	72	76
C.B LENGTH fr NECKHOLE	66	68	70	72	74	76	78	80
SLEEVE LENGTH	66,5	68	69,5	71	72,5	74	75,5	77

All measurements are indicated with tolerance of 1 cm