



# Ultra Cut Turbo

XP3000 - 50cm wide



Class 1

REACH Compliant

## STEP BY STEP

### Step 1

Cut your design in mirror image **Film blade required (90 - 100gf)**

### Step 2

Weed away any excess material

### Step 3

Place transfer face down onto the garment with the transparent backing on top and press for the required time and temperature for the textile being used

### Step 4

Remove the transparent backing hot or cold

#### MICRONS

95µ

#### FINISH

Matt

#### TACK

Very High

#### PEEL

Hot or Cold

#### PU or PVC

PU

## PRODUCT INFORMATION

SIZE: 50cm wide x 5 & 25m rolls  
CUTTING FORCE: 90 - 100gf (Film Blade)  
TRANSFER LAYERING: Yes (excluding metallics and fluorescents)

## SUITABLE FOR

- ▶ Cotton
- ▶ Polyester
- ▶ Polyester/Cotton
- ▶ Uncoated Nylon

## TRANSFER SETTINGS

TIME & TEMPERATURE	Polyester:	130°C - 5 seconds
	Polycotton:	130°C - 5 seconds
	Cotton:	130°C - 5 seconds 150°C - 4 seconds 160°C - 3 seconds
	Uncoated Nylon:	150°C - 5 seconds +5
PRESSURE	Medium	
PEEL	Hot or Cold	

## CARE INFORMATION

POLY-COTTON	POLYESTER	COTTON	UNCOATED NYLON	▶ Can be tumble dried ▶ <b>Do not</b> iron
60°C wash	60°C wash	40°C wash	40°C wash	

**PLEASE NOTE:** A4 samples are available free of charge upon request, for larger samples 1m rolls are available for purchase.

**PLEASE NOTE:** The sellers and manufacturers maximum obligation shall be to replace any product that has been proven to be defective. Neither the seller nor the manufacturer of Ultra Cut Turbo shall be liable for any injury direct or consequential, arising out of the use of, or inability to use this range. Ultra Cut Turbo has been tested using Kustom Kit garments, when applying to other garment brands results may vary, testing prior to purchase is recommended.

Oakridge Park, Trent Lane  
Castle Donington, Derby  
DE74 2PY

Phone: 01332 855 085  
Web: [www.xpres.co.uk](http://www.xpres.co.uk)  
E-mail: [sales@xpres.co.uk](mailto:sales@xpres.co.uk)  
Support: [www.xprestechnical.co.uk](http://www.xprestechnical.co.uk)