



# Sparkle

XP3014 - 50cm wide

## STEP BY STEP

### Step 1

Cut your design in mirror image **Flock blade required (140 - 180gf)**

### Step 2

Weed away any excess material

### Step 3

Place transfer face down onto the garment with the transparent backing on top and press for 15 seconds at 160°C

### Step 4

Remove the transparent backing cold

#### DURABILITY

40°C  
inside out

#### MICRONS

110µ

#### FINISH

Gloss

#### TACK

Medium

#### PEEL

Cold

#### PU or PVC

N/A

## PRODUCT INFORMATION

SIZE:	50cm wide x 5 & 25m rolls
CUTTING FORCE:	140 - 180gf (Flock Blade)
TRANSFER LAYERING:	No

## SUITABLE FOR

- ▶ Cotton
- ▶ Polyester
- ▶ Polyester/Cotton

Uncoated garments only

## TRANSFER SETTINGS

TIME	15 seconds
TEMPERATURE	160°C
PRESSURE	Medium
PEEL	Cold

## CARE INFORMATION

- ▶ Up to 40°C inside out
- ▶ Can be tumble dried
- ▶ **Do not** iron

**PLEASE NOTE:** A4 samples are available free of charge upon request, for larger samples 1m rolls are available for purchase.

**PLEASE NOTE:** The sellers and manufacturers maximum obligation shall be to replace any product that has been proven to be defective. Neither the seller nor the manufacturer of Sparkle shall be liable for any injury direct or consequential, arising out of the use of, or inability to use this range. Sparkle has been tested using Kustom Kit garments, when applying to other garment brands results may vary, testing prior to purchase is recommended.

Oakridge Park, Trent Lane  
Castle Donington, Derby  
DE74 2PY

Phone: 01332 855 085  
Web: [www.xpres.co.uk](http://www.xpres.co.uk)  
E-mail: [sales@xpres.co.uk](mailto:sales@xpres.co.uk)  
Support: [www.xprestechnical.co.uk](http://www.xprestechnical.co.uk)