

Super Flex[®] XP3016 - 50cm wide



STEP BY STEP

Step 1

Cut your design in mirror image Film blade required (90 - 100gf)

Step 2

Weed away any excess material

Step 3

Place transfer face down onto the garment with the transparent backing on top and press for 10 seconds at 150°C

Step 4

Remove the transparent backing cold

DURABILITY	MICRONS	FINISH	ТАСК	PEEL	PU or PVC	
80°C	50-60µ	Semi Matt	Medium	Cold	PU	
PRODUCT INFORMATION						
SIZE:			50cm wide x 5 & 20m rolls			

CUTTING FORCE: TRANSFER LAYERING: 90 - 100gf (Film Blade) Yes (excluding metallics)

PLEASE NOTE: Re-press for 5 seconds after the removal of the backing when multi transfer layering.

SUITABLE FOR

- Cotton
- Polyester
- Polyester/Cotton

Uncoated garments only

TRANSFER SETTINGS

TIME	10 seconds		
TEMPERATURE	150°C		
PRESSURE	Medium		
PEEL	Cold		

CARE INFORMATION

- ▶ Up to 80°C (Up to 40°C inside out when transfer layering)
- Can be tumble dried
- Do not iron

PLEASE NOTE: A4 samples are available free of charge upon request, for larger samples 1m rolls are available for purchase.

PLEASE NOTE: The sellers and manufacturers maximum obligation shall be to replace any product that has been proven to be defective. Neither the seller nor the manufacturer of Super Flex shall be liable for any injury direct or consequential, arising out of the use of, or inability to use this range. Super Flex has been tested using Kustom Kit garments, when applying to other garment brands results may vary, testing prior to purchase is recommended.

Oakridge Park, Trent Lane Castle Donington, Derby DE74 2PY Phone:01332 855 085Web:www.xpres.co.ukE-mail:sales@xpres.co.ukSupport:www.xprestechnical.co.uk