

JOBMAN

Size chart in cm



Brand; Jobman workwear
Style; 5400 Sweatshirt Hoodie

Position	XXS	XS	S	M	L	XL	2XL	3XL	4XL
1/2 CHEST	44	47	50	53	56	60	64	68	72
1/2 BOTTOM above rib	43	46	49	52	55	59	63	67	71
C.B LENGTH fr HPS (see sketch)	62	65	68	71	74	77	79	81	83
SLEEVE LENGTH	63	64,5	66	67,5	69	70,5	72	73,5	75

All measurements are indicated with tolerance of 1 cm